#### **ENVIRONMENTAL CHEMISTS**

Client:

# Analysis For Total Metals By EPA Method 200.8

Client ID: M130181 Date Received: 04/05/12 Date Extracted: 04/06/12 04/06/12 Date Analyzed: Matrix: Water Units: ug/L (ppb)

Alaskan Copper Works Project: Metro Self Monitor PO M130181 Lab ID: 204070-01 x10 Data File: 204070-01 x10.038 Instrument: ICPMS1 AP

Operator: Lower

Upper Internal Standard: Limit: Limit: % Recovery: 60 125 Germanium 87

Concentration Analyte: ug/L (ppb) Chromium 351 Nickel 257 Copper 469 Zinc 24.5

## **ENVIRONMENTAL CHEMISTS**

# Analysis For Total Metals By EPA Method 200.8

Client ID: Date Received: Date Extracted: Method Blank Not Applicable

Not Applicable 04/05/12 04/06/12

Date Analyzed: 04/06/12 Matrix: Water Units: ug/L (ppb) Client: Project:

Alaskan Copper Works Metro Self Monitor PO M130181

Lab ID: Data File:

I2-235 mb I2-235 mb.016 ICPMS1

Instrument: IC Operator: A

Internal Standard: Germanium

% Recovery: 103 Lower Limit: 60

Upper Limit: 125

Concentration

Analyte:

ug/L (ppb)

 Chromium
 <1</td>

 Nickel
 <1</td>

 Copper
 <1</td>

 Zinc
 <1</td>

## **ENVIRONMENTAL CHEMISTS**

Date of Report: 04/12/12 Date Received: 04/05/12

Project: Metro Self Monitor PO M130181, F&BI 204070

# QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 204014-01 (Matrix Spike)

				Percent	Percent		
	Reporting	$\mathbf{Spike}$	Sample	Recovery	Recovery	Acceptance	RPD
Analyte	Units	Level	Result	MS	MSD	Criteria	(Limit 20)
Chromium	ug/L (ppb)	20	<1	103	95	71-130	8
Nickel	ug/L (ppb)	20	35.8	<b>10</b> 3 b	94 b	71-120	9 b
Copper	ug/L (ppb)	20	1.60	95	97	52-134	2
Zinc	ug/L (ppb)	50	<1	96	98	51-142	2

Laboratory Code: Laboratory Control Sample

	Percent										
	Reporting	Spike	Recovery	Acceptance							
Analyte	Units	Level	LCS	Criteria							
Chromium	ug/L (ppb)	20	97	80-119							
Nickel	ug/L (ppb)	20	104	83-119							
Copper	ug/L (ppb)	20	103	81-120							
Zinc	ug/L (ppb)	50	102	82-120							

#### **ENVIRONMENTAL CHEMISTS**

## Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- ${
  m jl}$  The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr-The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- x The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

204070	MELE CHAIN OF CUSTODY	ME 04/0.	5/12 AIY
Send Report To IERAW Tho MASON	SAMPLERS (signature)	N	Page # of
Comment DIASKAN CORRE LABORIES	PROJECT NAMENO.  MELDO Self monitor	PO# M130/81	Standard (2 Weeks)  ONUSH S CO  Rush charges authorized by:
City, State, ZIP Septile List 98134	REMARKS	= 1	SAMPLE DISPOSAL  Dispose after 30 days
Phone # 206-57/-6077 Fax # 206-382-4309			Return camples     Will call with instructions

										ANA	HALYBES REXP				ed			
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel	TPH-Casoline	HTEX by 8021B	VOCs by 8380	SVOCe by 8270	HFS	Chlunder	*					Notes
m180181	01	4/5/12	12:30	HO	/				$\neg$		7	K						
353		7,							7		1					T		
			- 16 g				1	7	1	7	7					1		
V	,						7	7	7	1	1	7				$\top$	en Kere	
				•		1	7		1	1	1	1				$\neg$		Winter Commence
						7	1	$\exists$	1	1	7							
4						$\exists$	7	7	1	7	+	1	1		$\neg$	$\dashv$		
						7	7	7	7	7	7	7	1	7	7	$\forall$		38
						1	1	7	1	†	1	7	7	1	7	$\top$		
	1.					7	7	7	7	7	+	7	7	7	7	十		
de Bruye, Inc.	REGNATTINE Redinguished by:				PRINT NAME					Ţ	COMPANY					DA		TDE
Avenue West				Son												14/5	1/2	1:35pi
mile, WA 98119-2029 s. (206) 285-8882				Whan	Nhan Phan						Feb.T						1/2	V_
Par (206) 263-5044 Received by:								+	_									
BECCCE DOC										L	- 21					16		

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

April 12, 2012

Gerald Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on April 5, 2012 from the Metro Self Monitor PO M130181, F&BI 204070 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0412R.DOC